

EVERGREEN PLAYFIELD #1 EXISTING CONDITIONS



Above: Recently vandalized lights.

Top Right: Aerial view of field showing poor drainage

Bottom Right: NW backstop and ball diamond, no permanent bases installed.

Below: View from sidewalk/street, not aesthetically pleasing.



EVERGREEN PLAYFIELD #1 EXISTING CONDITIONS

Right: Girls Fastpitch
team practices



Left: Youth soccer
team practices



Right: Steel frame
goal, very heavy
and difficult to
move

